





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb  
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu







**Position**

- |                   |                   |
|-------------------|-------------------|
| 1 = A 962 872 XX  | 14 = A 962 529 NU |
| 3 = A 962 998 NU  | 15 = A 961 332 NU |
| 4 = A 962 870 XX  | 18 = A 962 594 NU |
| 5 = A 962 871 XX  | 19 = A 961 810 NU |
| 6 = A 963 427 NU  | 20 = A 962 595 NU |
| 7 = A 962 229 NU  | 21 = B 960 242 XX |
| 8 = A 962 230 NU  | 22 = A 961 073 XX |
| 9 = A 963 432 NU  | 24 = A 963 651 NU |
| 10 = A 962 563 NU | 25 = A 960 395 NU |
| 12 = A 962 568 NU | A 960 196 NU      |







**CERATHERM 100**  
 A 4623 .. A 4624 ..

0910 / A 866 247  
 (+ A 865 612)  
 Made in Germany



Ideal Standard  
 Roentgenstrasse 9  
 54516 Wittlich  
 Germany





	<b>P</b>	bar		MAX. 10		5			<b>Q</b> (3 bar)
	<b>T</b>	°C		MAX. 80		65			l/min
				40		55			<b>21,5</b>

