



Ordering spares / Ersatzteil - Regelung / Pièces de rechange / Parti di ricambio / Lista de recambios / Onderdelen bestellen (NL/B) / Κωδικό Ανταλλακτικών / Bestilling af reservedele / Beställning av reservdelar / Bestilling av reservedeler / Резервни части / Запчасти / Części zapasowe / Piese de schimb / Rendelhető alkatrészek / Запасні частини / Резервни делови / Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezerves daļas / Náhradní díly / Náhradné diely / Yedek parça siparişi / Nadomestni deli

XX = AA, AD,



- 1 - B 961523 XX
- 1a - B 961524 XX
- 3 - A 961157 XX
- 4 - B 960223 NU
- 5 - B 961326 NU
- 6 - H 960104 NU - R
H 960136 NU - L
- 8 - B 964667 NU
- 10 - B 961063 NU
- 11 - B 964666 NU
- 13 - B 960839 NU
- 14 - B 961525 XX
- 15 - A 860998 XX
- 16 - B 964562 XX





CERALINE

10.2020 / B665804

B C196 ..





	P	bar	0,5	MAX. 10	1			Q (3 bar)
	T	°C		MAX. 80				l/min
								13

