





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA,AD



Position

- 1 = A 960 645 XX
- 3 = B 960 473 XX
- 5 = A 960 646 XX
- 9 = A 962 985 NU
- 19 = A 960 678 NU
- 21 = A 962 385 XX
- 22 = A 960 197 NU
- 23 = A 960 679 XX
- 26 = A 960 654 XX
- 29 = A 961 230 XX
- 30 = A 960 196 NU




















ATTITUDE
 A 4602 ..

0909 / A 866 007
 (+ A 865 612)
 Made in Germany



Ideal Standard
 Roentgenstrasse 9
 54516 Wittlich
 Germany





	P bar	0,5	MAX. 10		5		Q (3 bar)
	T °C		MAX. 80		65		I/min
					40		13