








Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb  
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA, AD...

Position


- 1 = A 961 449 XX
- 2 = A 961 823 XX
- 3 = A 961 824 NU
- 4 = E 960 575 NU
- 7 = A 961 825 XX
- 8a = A 961 302 NU
- 8b = S 960 193 NU
- 10 = A 962 991 XX
- 11 = A 963 404 NU
- 12 = A 960 016 NU
- 13 = A 961 838 XX
- 14 = A 962 140 NU





**CERAPLUS**  
 A 4091 .. A 4092 ..

0211 / A 865 721 40  
 (+ A 865 612)  
 Made in Germany


A 4091 ..











A 4092 ..



Ideal Standard  
 Roentgenstrasse 9  
 54516 Wittlich  
 Germany





	<b>P</b>	bar				<b>Q</b> (3 bar)
	<b>T</b>	°C				l/min
						8

